



BOCA DE TORMENTA	TIPO DE TAPA			MATERIAL DE TAPA		MATERIAL DE CONECCION (VARILLERO)		COMENTARIO
	BANQUETA	ARROYO	CONCRETO	IRVING	OTRA	SI	NO	
307		✓		✓		✓		
308		✓		✓		✓		
309		✓		✓		✓		
310		✓		✓		✓		
311		✓		✓		✓		
312		✓		✓		✓		
313		✓		✓		✓		
314		✓		✓		✓		
315		✓		✓		✓		
316		✓		✓		✓		
317		✓		✓		✓		
318		✓		✓		✓		
319		✓		✓		✓		
320		✓		✓		✓		
321		✓		✓		✓		
322		✓		✓		✓		
323		✓		✓		✓		
324		✓		✓		✓		
325		✓		✓		✓		
326		✓		✓		✓		
327		✓		✓		✓		
328		✓		✓		✓		
								JUEVES 21/07/16
								SE VISITARON 328 BOCAS DE TORMENTA
								NO SE LIMPIARON 07 POR TENER VEHICULO
								SE LIMPIARON Y VARILLARON 321 BOCAS DE TORMENTS 50X60

[Handwritten signatures and initials]

