

241	✓	✓	✓	✓	✓	✓
242	✓	✓	✓	✓	✓	✓
243	✓	✓	✓	✓	✓	✓
244	✓	✓	✓	✓	✓	✓
245	✓	✓	✓	✓	✓	✓
246	✓	✓	✓	✓	✓	✓
247	✓	✓	✓	✓	✓	✓
248	✓	✓	✓	✓	✓	✓
249	✓	✓	✓	✓	✓	✓
250	✓	✓	✓	✓	✓	✓
251	✓	✓	✓	✓	✓	✓
252	✓	✓	✓	✓	✓	✓
253	✓	✓	✓	✓	✓	✓
254	✓	✓	✓	✓	✓	✓
255	✓	✓	✓	✓	✓	✓
256	✓	✓	✓	✓	✓	✓
257	✓	✓	✓	✓	✓	✓
258	✓	✓	✓	✓	✓	✓
259	✓	✓	✓	✓	✓	✓
260	✓	✓	✓	✓	✓	✓
261	✓	✓	✓	✓	✓	✓
262	✓	✓	✓	✓	✓	✓
263	✓	✓	✓	✓	✓	✓
264	✓	✓	✓	✓	✓	✓
265	✓	✓	✓	✓	✓	✓
266	✓	✓	✓	✓	✓	✓
267	✓	✓	✓	✓	✓	✓
268	✓	✓	✓	✓	✓	✓
269	✓	✓	✓	✓	✓	✓
270	✓	✓	✓	✓	✓	✓
271	✓	✓	✓	✓	✓	✓
272	✓	✓	✓	✓	✓	✓
273	✓	✓	✓	✓	✓	✓
274	✓	✓	✓	✓	✓	✓
275	✓	✓	✓	✓	✓	✓
276	✓	✓	✓	✓	✓	✓
277	✓	✓	✓	✓	✓	✓
278	✓	✓	✓	✓	✓	✓
279	✓	✓	✓	✓	✓	✓
280	✓	✓	✓	✓	✓	✓
281	✓	✓	✓	✓	✓	✓
282	✓	✓	✓	✓	✓	✓
283	✓	✓	✓	✓	✓	✓
284	✓	✓	✓	✓	✓	✓
285	✓	✓	✓	✓	✓	✓
286	✓	✓	✓	✓	✓	✓
287	✓	✓	✓	✓	✓	✓
288	✓	✓	✓	✓	✓	✓
289	✓	✓	✓	✓	✓	✓
290	✓	✓	✓	✓	✓	✓
291	✓	✓	✓	✓	✓	✓
292	✓	✓	✓	✓	✓	✓
293	✓	✓	✓	✓	✓	✓
294	✓	✓	✓	✓	✓	✓
295	✓	✓	✓	✓	✓	✓
296	✓	✓	✓	✓	✓	✓
297	✓	✓	✓	✓	✓	✓
298	✓	✓	✓	✓	✓	✓
299	✓	✓	✓	✓	✓	✓
300	✓	✓	✓	✓	✓	✓
						SE VISITARON 300 BOCAS DE TORMENTA
						DE LAS CUALES 268 SON DE 50X60
						Y 32 SON DE 3 PICOS
						NO SE LIMPIARON 14 DE 50X60 POR TENER VEHICULO
						SE LIMPIARON Y VARILLARON 254 BOCAS DE TORMENTA DE 50X60
						SE LIMPIARON Y VARILLARON 32 BOCAS DE TORMENTA DE 3 PICOS
						SE BONIFICAN 30 POR SER DOBLES LIMPIEZA UNICAMENTE

Handwritten signature/initials

